

from 1st two 1501's and  
dcc system

**Rear**

power supply  
to wall outlet

next 1501



this plate loses one plug port

**Front**

**5th plate should be  
a powered one**

no AD493  
needed