

**Every 5th Extension Plate should be an 0001502
Powered Extension Plate To Prevent Volt Drop In
The Throttle Bus**

